FIG. 1




FIG. 2A




FIG. 2B METALLIZATION RATIO = 0.75 h/λ2. 0% 0 A2 10 INSERTION LOSS (dB) -0. 0 Y6 20 -2. 0 Y5, **3**0 Y4、 4. 0 40 -6. 0 50 -8. 0 60 FREQUENCY

FIG. 3A




FIG. 3B







FIG. 4



RANGE WHERE RIPPLE CAUSED BY TRANSVERSE-MODE WAVE CAN BE REDUCED FIG. 5










FIG. 8

RANGE WHERE RIPPLE CAUSED BY TRANSVERSE-MODE WAVE CAN BE REDUCED (W-IDT /CRYSTAL)









FIG. 11






FIG. 13

